

CPM Pneumatic Motors



Pneumatic Hand Motors for worn effects

	CPM-1	CPM-2	CPM-3
Processing Air Requirement	6 Bar	6 Bar	6 Bar
R.P.M	1400	22000	22000